Play Area Equipment Report 2022

10th November 2022

South Avenue Recreation Grounds

Play Equipment on Site

- Swing – Toddler 1 Bay, 2 Seats.
- Carousel – Roundabout.
- Rocker – Seesaw, Multi Seat.
- Rocker – Horse, Double Seated.
- Swing – Hammock.
- Climber – Space Net, with Slide.
- Multi play – Junior.
- Trampoline.
- Swing – 2 bays, 1 basket, 2 seats.
- Climber – Bloqx
- Carousel – Overhead.

Other items on Site

- 1 x Picnic Table.
- 5 x Benches.
- 2 x litter bins.
- 2 x Trees.
- 2 x pedestrian gate access.
- 1 x Vehicle gate access.

Play Area Equipment Report 2022

10th November 2022

Swing – Toddler 1 Bay 2 Seats

Repairs

- One seat replaced February 2022; other seat is in good condition at present.

New

Old

ROSPA report

Low Risk

Recommended repairs/Actions

- Shackle bolt checked for wear, replace at 70% of original diameter (at 30% presently).

Play Area Equipment Report 2022

10th November 2022

Carousel – Roundabout

Repairs

- No recent repairs.

ROSPA report

Medium Risk

Recommended Repairs/Actions

- Bearings require servicing.
- Paintwork is on Poor condition, de-scale back to good base and coat with lead free paint.

Play Area Equipment Report 2022

10th November 2022

Rocker – Seesaw – Multi-Seat

Repair

- No Recent Repairs.

ROSPA Report

Low Risk

Recommended repairs/Actions

- Tighten loose bolts on Footrest bars
- Tail of Dolphin side panel damaged and needs repairing.
- Edges of laminated central platform requires edges to be rubbed down.

Future recommendations

- No future recommendations.

Play Area Equipment Report 2022

10th November 2022

Rocker – Horse – Double Seated

Repair

- No Recent Repairs.

ROSPA Report

Low Risk

Recommended repairs/Actions

- *bolts require tightening.*
- *Safety bar needs tightening.*
- *Seat edges needs rubbing down and treating.*

Future recommendations

- No future recommendations.

Play Area Equipment Report 2022

10th November 2022

Swing – Hammock

Repair

- No Recent Repairs.

ROSPA Report

Low Risk

Recommended repairs/Actions

- *No Repairs or Actions required.*

Future recommendations

- *Look to improve surface under the Hammock by adding rubber mulch.*

Play Area Equipment Report 2022

10th November 2022

Climber – Space Net – With Slide

Repair

- No Recent Repairs.

ROSPA Report

Low Risk

Recommended repairs/Actions

- *No Repairs or Actions required.*

Future recommendations

- No future recommendations.

Play Area Equipment Report 2022

10th November 2022

Multi play – Junior

Repair

- No Recent Repairs.

ROSPA Report

Low Risk

Recommended repairs/Actions

- *Cap Missing and requires replacing.*

Future recommendations

- No future recommendations.

Play Area Equipment Report 2022

10th November 2022

Trampoline

Repair

- No Recent Repairs.

ROSPA Report

Medium Risk

Recommended repairs/Actions

- *Rubber edging loose and requires re-securing.*
- *Trapped Frogs and toads to be rescued each year.*
- *Trip points on surface around trampoline, needs levelling.*

Future recommendations

- *Possible remove equipment.*
- *If kept look to improve surface around Trampoline with rubber mulch.*

Play Area Equipment Report 2022

10th November 2022

Swing – Mixed – 2 bay 1 basket 2 Junior Seats

Repair

- Replaced joint on chain (research further)

ROSPA Report

Medium Risk

Recommended repairs/Actions

- Replace chains before 40% wear, at Wearing limit and need replacing.
- Inspect and replace any worn chains or parts.
- Basket swing rope fraying in small places, monitor for any broken strands and replace when necessary.

Future recommendations

- Look to improve surface, by installing wet pour surface under the swings to prevent ground wearing.

Play Area Equipment Report 2022

10th November 2022

Climber – Bloqx

Repair

- No Recent repairs required.

ROSPA Report

Medium Risk

Recommended repairs/Actions

- No Repairs or actions required.

Future recommendations

- No future recommendations.

Play Area Equipment Report 2022

10th November 2022

Carousel – Overhead

Repair

- No Recent repairs required.

ROSPA Report

Medium Risk

Recommended repairs/Actions

- Replace worn matting and resecure separating mat.

Future recommendations

- Look to add wet pour surface around this equipment.

Play Area Equipment Report 2022

10th November 2022

Picnic Bench

Recommended repairs/Actions

- Some arson damage, central strut requires repairs.

Benches

5 Benches are presently in South Avenue Recreation Grounds.

Recommended repairs/Actions

- No Repair or Actions needed at this time.

Play Area Equipment Report 2022

10th November 2022

Trees

1 x Oak Tree – Good condition, with low branches used by children to play on.

1 x Horse Chestnut Tree – To be felled, sail to be reduced October 2022, tree to be felled once new tree established in similar area, but not to the South of Tennis court.

Gates

We have 2 pedestrian and one vehicle gate into this Play Area, some minor repairs required.

Play Area Equipment Report 2022

10th November 2022

Reeds Lane Recreation Grounds

Fitness Equipment

- 1 x Chest Press – Twin.
- 1 x Air Walk.
- 1 x leg Push – Twin.
- 1 x Cross Trainer.

Play Equipment on Site

- 1 x Multi Play – Toddler.
- 1 x Rocker – Bird.
- 1 x Swing – Junior, 1 bay 2 Seats.
- 1 x Swing – Toddler, 1 bay, 2 seats.
- 1 x Swing – Basket.
- 1 x Agility – Wobble Board.
- 1 x Climber – A Frame & Net.
- 1 x Agility Trail.

Additional Items on Site

- 2 x Benches.
- 1 x Litter Bin.
- 2 x Pedestrian Gate access.
- 1 x Vehicle Gate access.



Play Area Equipment Report 2022

10th November 2022

Fitness Equipment

Chess Press – Twin

Repair

- No Recent repairs.

ROSPA Report

Low Risk

Recommended Repairs/Actions

- Paintwork needs refreshing.

Future Recommendations

- No future Recommendations.

Play Area Equipment Report 2022

10th November 2022

Air Walk

Repair

- No Recent repairs.

ROSPA Report

Medium Risk

Recommended Repairs/Actions

- Fixings Loose or Missing – Arm 1 loose.
- Paintwork needs refreshing.
- Provide damping to reduce impact damage.

Future Recommendations

- No Future Recommendations.

Play Area Equipment Report 2022

10th November 2022

Leg Push – Twin

Repair

- ***No Recent Repairs.***

ROSPA Report

Low Risk

Recommended Repairs/Actions

- ***Paintwork needs refreshing.***

Future Recommendations

- ***No Future Recommendations***

Play Area Equipment Report 2022

10th November 2022

Cross Trainer

Repairs

- No Recent Repairs

ROSPA Report

Low Risk

Recommended Repairs/Actions

- Replace Bolt Cap

Future Recommendations

- No Future Recommendations

Play Area Equipment Report 2022

10th November 2022

Multi play – Toddler

Repair

- No Recent repairs required.

ROSPA Report

Low Risk

Recommended repairs/Actions

- Replace missing cap on handle fitting.
- Tighten loose fixture by slide.
- Strimmer damage on ground level posts, speak to contractor.

Future recommendations

- No Future Recommendations

Play Area Equipment Report 2022

10th November 2022

Rocker – Bird



Repair

- No Recent repairs required.

ROSPA Report

Low Risk

Recommended repairs/Actions

- No Repairs/Actions required.

Future recommendations

- No Future Recommendations

Play Area Equipment Report 2022

10th November 2022

Swing – Junior – 1 Bay 2 Seats

Repair

- No Recent repairs required.

ROSPA Report

Low Risk

Recommended repairs/Actions

- Tighten Hangers.
- Matting missing and separating under swings and needs repairing or replacing.

Future recommendations

- No Future Recommendations

Play Area Equipment Report 2022

10th November 2022

Swing – Toddler – 1 Bay 2 Seats

Repair

- No Recent repairs required.

ROSPA Report

Medium Risk

Recommended repairs/Actions

- Tighten Hangers.
- Check support beams for rot

Future recommendations

- No Future Recommendations

Play Area Equipment Report 2022

10th November 2022

Swing – Basket

Repair

- No Recent repairs required.

ROSPA Report

Low Risk

Recommended repairs/Actions

- No Repairs /Actions required.

Future recommendations

- No Future Recommendations

Play Area Equipment Report 2022

10th November 2022

Agility – Wobble Board

Repair

- No Recent repairs required.

ROSPA Report

Low Risk

Recommended repairs/Actions

- No Repairs /Actions required.

Future recommendations

- No Future Recommendations

Play Area Equipment Report 2022

10th November 2022

Climber – A-Frame & Net

Repair

- No Recent repairs required.

ROSPA Report

Low Risk

Recommended repairs/Actions

- No Repairs /Actions required.

Future recommendations

- No Future Recommendations

Play Area Equipment Report 2022

10th November 2022

Agility Trail

Repair

- No Recent repairs required.

ROSPA Report

Low Risk

Recommended repairs/Actions

- No Repairs /Actions required.

Future recommendations

- Some wear under the equipment, may need to look at surfacing in the future.

Play Area Equipment Report 2022

10th November 2022

Goal Posts

Repairs

- Damage Net recently removed from West Goal Posts.

Recommended Repairs/Actions

- Rusty treated and removed and painted.

Future Recommendations

- Level ground and reseed, install small goal post to fit area better.

Play Area Equipment Report 2022

10th November 2022

Additional Items

Benches

- 2 x Benches in Toddler Play Area Only

Bin

- 1 x Small plastic Bin – to be moved to Toddler fence.

Gates

- 2 x Pedestrian Gate access
    - 1 x Roadside
    - 1 x Toddler play area.
- 1 x Vehicle Gate Access – (Metal).

Fencing

- Toddler Play Area
- Junior Play Area – Fencing has been cleared.
- Ditch on Southern Boundary – S106 application to be submitted.

Hard Surfacing

- 1 x Resin Path from Road to Toddler and Junior Play Area.